



Re : Dewhurst Part number – 002099-400011 CJ40 24V EN BUZZ

It was just brought to my attention that the wires shipped in the latest batch of EN Buzz's have the **Red and White wires swapped on the PCB solder terminals PC and PR** . This means that the Buzzer **would not work**. Please see the photo below .



Immediate suggested **CORRECTIVE ACTION**– swap RED and WHITE wires at the connector end as shown below, i.e. White to PR and Red to PC. The buzzer will then work.



Authorised Signatory

SreeDevi Aleddula
Quality Manager

Dewhurst Ltd

Unit 9 Hampton Business Park, Hampton Road West, Feltham, TW13 6DB
tel +44 (0)20 8744 8200 info@dewhurst.co.uk www.dewhurst.co.uk

Registered office: as above Registered no: 06834598